



Panasonic 3DO FZ-10 POWER SUPPLY (120V, 30W) schematic diagram

ETXMM002A2B
NPX002A2-1B

Nº	1	2
	~120V	~120V

CN001 "LINE AC ~120V"

Nº	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18
	+9V	+9V	+9V	GND	GND	GND	GND	GND	GND	GND	GND	GND	+5V	+5V	+5V	+5V	+5V	~5V

CN101