



T1  
AC 120V/60Hz to AC 15V - Step Down Transformer

No	T1 coil	R coil winding (Ohm)
I		22 Ohm (to DC)
II		1,1 Ohm (to DC)

Panasonic 3DO FZ-1 POWER SUPPLY (120V, 30W) schematic diagram  
(NTSC - US region)

Watchdog